

FITNESS CENTER RENOVATION RONALD REAGAN BUILDING WASHINGTON, DC



FITNESS CENTER RENOVATION

Renovation Overview


Main Fitness Center Area

- New athletic rubber flooring
- Redesigned entrance area - floor, ceiling and lighting
- New reception desk and sign-in area
- New flat panel HDTVs
- New fans to increase air circulation
- New paints, colors and wallcovering
- New column cover accents with protective finishes
- New carpet in offices
- Enhanced lighting

Locker and Shower Area

- Improved ventilation and optimized HVAC
- New water conserving shower heads
- New handicapped shower stall seats
- Repaired tile work
- New mirrors and refurbished counters at sink areas
- New wallcovering, paint and accents
- Improved floor drainage
- Repaired drywall and new paint throughout

FITNESS CENTER RENOVATION



New Finish Plan - Ronald Reagan Building - Fitness Center

Finish Materials

- | | | | |
|---|--|---|--|
| ● RF-1: Resilient Floor covering - Rubber (Black with speckles) | ● RF-4: Resilient Floor covering - Rubber (Red) | ● RWC-1: Accent Wallcovering (Columns, Men's Vestibulo) | ● FWP-3: Accent Wallcovering (Entrance niche areas and) |
| ● RF-2: Resilient Floor covering - Rubber (Blue w/ specs) | ● RF-5: Resilient Floor covering - Rubber (Yellow) | ● RWC-2: Accent Wallcovering (Columns, Women's Vestibulo) | ● PT-1: Accent Paint in Men's Locker Rooms |
| ● RF-3: Resilient Floor covering - Rubber (Blue w/o specs) | ● CPT-1: Carpet | ● RWC-3: Accent Wallcovering (Columns & Entrance) | ● PT-2: Accent Paint in Women's Locker Rooms |

FITNESS CENTER RENOVATION

